

DATE 2012Z 27 OCT 63

SECRET

2	4
3	5
6	6

PRIORITY

IN 97607

TO DIRECTOR

25X1A FROM [REDACTED]

ACTION: OPS 1-7

INFO

TOR 0105Z 28 OCT 63

25X1A PRIORITY [REDACTED]

INFO [REDACTED]

DATE [REDACTED]

0102 25X1A

25X1A

A. G-3235

B. LMOD

C. VERY SMALL BLACK HAIRLINE EMULSION ABRASIONS ON 9R 13/16 INCH FROM TITLED EDGE AND DOWN CENTER OF FRAME PLUS SEVERAL OTHER INTERMITTENT ABRASIONS OF SAME TYPE FROM FRAME NO 2130 TO END OF FILM. INTERMITTENT ABRASIONS MOSTLY IN AND ALONG TITLED EDGE. THESE BELIEVED TO BE CAUSED BY CAMERA MAGAZINE SINCE BACK-UP TRAILER FROM SAME PROCESSOR SHOWS NO EVIDENCE OF MACHINE ABRASIONS. 9L ROLL SHOWS NO DEFECTS OF SIMILAR TYPE. ALSO SMALL HAIRLINE MARK ON 9R LOCATED NEAR EDGE OF DATA CHAMBER. APPEARS TO BE CAUSED BY SMALL PIECE OF LINT IN DATA CHAMBER.

END OF MESSAGE

SECRET

Excluded from automatic
downgrading and
declassification